

Iron Stream
Chain or
Steel Wire

H 225 121 748
H 220 127 654
OSAKA, JAPAN. 3-2-53 K. URAKAWA
Manila 2000

(Req. 1a.)

(Received at London Office) 20 - 10 - 53 19

No. Place Kobe Date October 5th 19 53

We request that the Committee of Lloyd's Register will instruct the Society's Surveyors to Specially Survey during Construction the Hull, Engines and Boilers of the Vessel No. S 31 building by Messrs. Fujinagata Shipbuilding Co., Ltd. for Messrs. Inui Kisen Co., Ltd. of 7,200 Tons. Length 134.00 m, Breadth 18.40 m, Depth 10.40 m intended to be Classed * 100A1 * LMC.

We undertake to arrange for every facility to be given to the Surveyors to carry out the duty in question, and we agree to pay the fees for the Surveyors' services, in addition to the actual travelling and other expenses incurred by the Surveyors in connection therewith.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of shipping, which provide that:-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society.

Auth
16/10/53

Engine Makers Mitsui Shipbuilding Co., Ltd. Tamano Works

Boiler Makers

Signature J. Kasaki
Managing Director

To the Secretary,
Lloyd's Register of Shipping, Fujinagata Shipbuilding Co., Ltd.
71, Fenchurch Street, London, E.C.3.

NOTE.—To avoid misunderstanding, orders for materials requiring to be tested should be marked as follows:—
"Inspection and Testing by Lloyd's Register Surveyors to the Society's requirements."

012165-012171-0156

