

S.S. "CHAMPADAH" Ex "HUNG SING"

This ship was built by Messrs. Swan Hunter & Wigham Richardson Ltd., at Wallsend on Tyne in 1919-4 and then classed #100A1.

The class was withdrawn at Owners' request 26.9.47.

In a letter dated 15.10.60 the Djakarta Surveyors state the ship has been sold and the new Owners are considering Reclassification.

IT IS SUBMITTED the Owners be advised, through the Djakarta Surveyors, that for Reclassification it will be necessary for:-

1. The requirements of a SPECIAL SURVEY (D) to be complied with, including the drilling of shell plating and strength deck amidships (Chapter C.231 of the Ship Rules) and in such parts of the structure where signs of wastage are evident.
2. Any major repairs which have been or are to be effected to the structure since the ship was disclassified to be specially examined in order to ascertain the character of the workmanship and confirm that the materials used are in accordance with the Rules.
3. Structural alterations which may have been carried out since the ship was disclassified to be specially examined in order to ascertain the character of the workmanship and conform that the materials used are in accordance with the Rules.
4. Structural alterations affecting the longitudinal and/or transverse strength of the ship which may be required at this time should be carried out in accordance with plans approved, and
5. full particulars of the equipment on board (which should be found or placed in accordance with Rule requirements) including weights and tests of anchors, also length, diameter and tests etc. of chain cable to be furnished.



4.11.60.

© 2021
Lloyd's Register
Foundation