

Received by me 31-10-60 g/g

LON.



LLOYD'S REGISTER OF SHIPPING

RECEIVED

22 OCT 1960

Ans d

Telegrams: Register, Djakarta

c/o Harrisons & Crosfield,

Teromol Pos Dak. 715,

Djakarta, Indonesia

15 October 1960

Reference

JAB/EM

S.S." CHAMPADAH"

Dear Sir,

This vessel (under the Flag of Thailand) was arrested in Indonesian waters some time ago by the Indonesian Authorities, for alleged smuggling or other illegal practise, and has been laying at the port of Tandjung Pinang, Riau Archipelago.

The ship has recently been purchased from the Indonesian Government by:-
P.T.PELAJARAN SINAR SEGARA, Djalan Arab No.1, MEDAN, Sumatera.

The Branch office of the Company at Singapore being SINAR SEGARA LINE, LTD., 23 Bussorah Street, SINGAPORE. Telephone 24391.)

The New Owner's have requested that the ship be entered in Lloyd's Register Book, it is not listed in the current edition. At present they are also considering classing the vessel with Lloyd's Register, I have explained to them the necessity of supplying ship and engine plans, etc:, of which there are none available, and in this respect they have enquired if it would be possible for Lloyd's Register, London to obtain these from the Builders.

The Owner's have also informed me that they have applied to the Indonesian Government for an alteration of foreign exchange to have the vessel towed to Singapore for repairs.

I shall be pleased to receive your comments on this case at your earliest convenience, also will you kindly advise me if the necessary plans can be obtained if required.

* allocation



© 2021

-page 2-

Lloyd's Register
Foundation

012236-012245-0062 1/2

Quarantine trace
this ship
Firm given as
Builders are
Engineers!

lx

Hung Sing
64868 in RB

* classed in
until 9/47

LLOYD'S REGISTER OF SHIPPING, DJAKARTA.

- 2 - The Secretary, London, 15 Oct.1960

A list of the only known particulars of the vessel is enclosed herewith. No previous names of the ship are known.

encl:

Yours faithfully,

J.A. Boater
J.A. Boater

✓ The Secretary,
London

Copies to:-
The Surveyors, Singapore.
The Surveyor, Bangkok.



© 2021

Lloyd's Register
Foundation

CLASSIFICATION
SHIP
~~EN~~
PUBLICATIONS

(Typed)
1. Submit surveys to inform etc
From the information so far received
we have no communication yet from Bangkok)
we cannot trace the ship. This name given for
builders on this form is in fact an engine builder
2. Unless the ship has been very well maintained
efficiency repairs are most likely to be necessary for
classification. we are prepared to endeavour to obtain plans
3. Nevertheless can be traced in the records.
J. V. Bourget
21/1/60

noted
21/1/60

the classification, number,
the classification, number,
copies to:-

the classification,
the classification,

the classification,

the classification,

© 2021



Lloyd's Register
Foundation

the classification,

the classification, number, etc.