

117 JUN 1954

ved by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

PS NAME "SANTO"

REPORT

Os l. No. 7490

JD.

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—*Extract from Sub-Committee's Report, 24/5/92.*)

A Half-time Survey becomes due 12,54.

Proposal to postpone examination in drydock until July, 1953 approved. See letter dated 29.5.53.

The OSLO Surveyors report 5,53 this ship afloat and alterations effected to hatchways in accordance with approved plan and Secretary's letter.

The ship has not been examined in drydock at this time and it is reported the Owner has stated each time he has been approached that the ship was expected to come into service at any moment and that outstanding surveys would be dealt with. The Surveyors recommend ship be drydocked before she is put into service again.

IT IS THEREFORE SUBMITTED the class be continued, subject to examination in drydock before resuming service.

See Mchy Bndsmnt.



© 2021

Lloyd's Register
Foundation

012246-012255-0031

ABM.
16.6.54.