

(Received at London Office, **26 FEB 1934**)

No. 1226 Port Leith.

Date 24th February 1934.

We request that the Single Screw Steam Vessel Building
for Stephenson Clarke & Assoc. Coys. Ltd. by The Burntisland Shipbuilding Co. Ltd
of 960 app Tons. Length, LML 204.0 breadth, old 32.10 depth, old 15.1
may be Specially Surveyed while building (+ 100A1)

If for a particular term or class, state the same.

We hereby engage to pay the established Special Survey Fees in accordance with the Society's Rules as follows, also the fees for inspection of installation of Electrical Fittings as set forth in the Society's Rules for Electric Fittings on board Vessels,

For ships built under the special superintendence of the Surveyors (to entitle them to the distinctive mark \clubsuit),
2s. per ton for the first 1,500 tons gross; 1s. per ton for every ton from 1,501 tons to 5,000 tons gross; 6d. per ton
than £20 0s. 0d.

50 per cent. to be added to these fees for the Special Survey during construction of Vessels for Carrying Oil in Bulk.
For engines and boilers built under the special superintendence of the Surveyors (to entitle them to the distinctive mark \clubsuit in red):—

Five shillings per Nominal Horse Power for the first 250 Horse Power; three shillings for each Horse Power from
251 to 500; one shilling for each Horse Power from 501 to 1,000; and 6d. for each Horse Power beyond 1,000. No fee to be
less than £15 0s. 0d.

The Nominal Horse Power for regulating survey fees on engines and boilers to be determined as described in Section 29.
For the survey and testing of Steam Boilers fitted in Diesel Engine Vessels additional fees will be charged in accordance with the
Society's usual scale.

For the survey and testing of each Vertical Donkey Boiler, a fee of four guineas will be charged.
Entry Fees as per Section 28 are additional to the above charges.

In exceptional cases an additional charge will be made according to the service performed, and in all cases where travelling
expenses are incurred by the Surveyors in connexion with the above services, they are to be defrayed by the parties interested.
In no case can the ship be classed until all fees, travelling expenses, &c., due thereon are paid.

This request is made upon the terms of the Rules and Regulations of Lloyd's Register of Shipping,
which provide that:—

While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be
understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy
in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the
Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society.

No. 149 in Builder's Yard.

Manufacturers of Engines David Rowan & Co. Ltd

Ditto of Boilers - ditto -

Signature

To the Secretary,

Lloyd's Register of Shipping,

71, Fenchurch Street, London, E.C.3.

FOR THE BURNTISLAND SHIPBUILDING COMPANY LTD.

Wm. Lowe

012446, 012459-0301

Vessel

Survey

Plating, Sheathing, material and thickness ...

30. *Material in ivory
Atteridlar only.*

SHEET

DEPART
PROVED
TO BE

ASB 999 08

hollow bolts



© 2021

Lloyd's Register
Foundation

STEEN
FRAME

Propeller Post *propeller*

478" *478"*

4
city

St

TT

.6