

Lloyd's Register of Shipping.

UNITED WITH THE BRITISH CORPORATION REGISTER
1, FAIRLIE PLACE.

Calcutta, 27th September, 1957.

ary,

S.S. "FIRISHTA"

Further to your letters regarding overdue surveys on the vessel. We visited the vessel afloat at Chittagong on the 15th and examined the boiler in its entirety. The boiler is good.

Requirements for Annual Load Line Survey were discussed with the Master and Government of East Pakistan representative in Calcutta. This survey will be held in due course.


No further information has been obtained regarding the Hull Survey and Screwshaft Survey also overdue. We have today advised the Government Department concerned regarding the foregoing and will advise you of the outcome.

As this vessel was requisitioned by the Government of East Pakistan, the Owners do not hold themselves responsible for overdue surveys.

The vessel is at present engaged in lightering duties within the limits of the Karnafuli River running between Chittagong and Comilla anchorage.

Yours faithfully,
for: THE SURVEYORS.

J. S. Cook



© 2021

Lloyd's Register
Foundation

012473-012482-0061

SB

CLASSIFICATION

H M

awaiting copy
and letter case re
JMG. BRING OUT R.A.F.
18/10/57

COPY TO F.B.D.

Calcula, 1957

Register of Shipping

COPIES REGISTER OF SHIPPING

COPY



© 2021

Lloyd's Register
Foundation

Secretary,
London.

Thanking

We shall
available
may recei
Authoriti
in the fu
our futur

and have
We thank

September
wing is t
s in this

Sir,

Ref: Cla