

38700

MEMORANDUM

**From : LLOYD'S REGISTER OF SHIPPING,** 71, FENCHURCH STREET,  
LONDON, E.C.3.

(Ref. R.)

**To:** The Surveyor(s) at

BUENOS AIRES


Date: 24th February, 1966

Vessel's Name:

M.S. "NORWID"

17 MAR 1966

SFA/BN



QUESTION

ANSWER


The Hull class of this vessel is at present subject to permanent repairs to the fractured forecastle deck plating, bulwark plating in way and No.1 hold ventilators, being effected on the vessel's arrival at Buenos Aires and by the end of January 1966.

With reference to your Return 3, dated 21st January, it is concluded that this matter was dealt with at this time, but your confirmation will be appreciated.



Date:— 9th. March 1966.

Dealt with our report No.  
38700 in process of preparation  
for early despatch referring.




© 2021

Lloyd's Register  
Foundation

012616 - 012619 - 0019