

Rpt. 9B

## REPORT OF MACHINERY SURVERYS AND REPAIRS

Received London

-7. MAR. 1966

Ship's Name ~~SS~~/MS "NORWID"  
IR-525791

Gross tons 7828

Is there a rpt. 8? No

Port BUENOS AIRES

Rpt. No. 38690

No. of visits Two

First date 26-1-66

Last date 31-1-66

Interim Cert. issued  
& copy herewith? YesDamage rpt. issued  
& copy herewith? NoLast rpt. (H.Q. only) *LD 11050*Date of  
completing rpt. 1-2-66

Surveyed at, if different from Port above -

Is a rpt. 9A  
attached? No

MN 1440

Nature of survey A.B.S.

Survey fees  
\$ 18,000.00

Damage fee -

Expenses  
\$ 600.00

S.A. fee -

## DOCKING

Propeller

Sea connections

Oil gland

Fastenings

Wear down of stern bush

Has screw/tube  
shaft been drawn?

Date of examn

Has shaft been  
changed?

Has shaft now fitted been previously used?

Has shaft now examined/fitted a continuous liner?

Approved oil gland?

BOILERS OPENED UP AND EXAMINED. (Identify by position and state latest date of internal examination of

AUXILIARY, ~~DONKEY~~ OR ~~DRUM~~ (State if oil fired—OF or exhaust gas—EG) ~~MAIN~~

each boiler.)

O.F. 26-1-66 - Good.

~~Air heaters~~~~Superheaters~~

Safety valves O.F. - Good

Mountings, doors  
and fastenings O.F. - GoodSafety valves | Sat O.F. - 85 lb - Good  
adjusted to | ~~Sp~~Boiler securing  
arrangements Good~~Main economisers~~~~Steam heated~~~~steam generators~~~~Forced~~

circulating pumps Both - Good

~~Have saturated steam pipes in cylindrical boiler  
smoke boxes been examined as required by the Rules?~~

Exhaust gas heated economisers

Good

Safety valve adjusted to 85 lb. - Good

~~Steam generator safety valves adjusted to~~

Funnel Good

Were oil burning system &  
remote controls examined  
in accordance with rules? Yes - Good

I recommend that the machinery of this ship remain as classed with/without fresh record of

A.B.S. 1/66 now.

(Where conditions of class are recommended to be  
retained, imposed, amended or deleted, particulars  
must be stated above and on the interim certificate.)

H.E. Schreiber

Surveyor to Lloyd's Register of Shipping

Date of Committee

Minute

ALSO FOR

SPL FOR

TRO

SRL

POSTING

HEADER

CERT

Lloyd's Register  
Foundation

012616-012619-0021

At part or complete Special Surveys those items which are not applicable to the ship are to be cancelled; When any part has been subjected to pressure test this should be stated. Engine parts when referred to by numbers should be counted from forward.

considered that re-examination or repairs should be made before that date a distinguishing mark must be inserted against the item and the circumstances and action taken or recommended described fully under "defects and repairs".

The condition of any item is to be described as "good" only when it has been examined, found or placed in good condition, and is considered to be acceptable until the due date of the next Periodical Examination. Where repairs have been effected or it is

See H.P. rept 3652



# EXAMINATION AND TESTING OF STEAM PIPES (state material)

MAIN  
 AUXILIARY  
 (over 3" bore)

Have saturated pipes in cylindrical boiler smoke boxes been tested?

Were selected copper pipes annealed?


## ELECTRICAL EQUIPMENT

PROPULSION (State Port—P, or Starboard—S)		AUXILIARY	
Total kW or kVA		Total kW or kVA	
a Generators		l Generators & governors	
b Exciters			
c Air coolers		m Motors	
d Motors			
e Air coolers		n Switchboards & fittings	
f Control gear cables, etc.		o Circuit breakers	
g Insulation resistance		p Cables	
h Insulating oil test		q Insulation resistance	
i Overspeed governors		r Steering gear generators & motors	
j Magnetic couplings		s Navigation light indicators	
k Air gap			

## PARTICULARS OF DEFECTS, REPAIRS, ALTERATIONS, ETC.

S.R.L. No.246 & Appendix - Clear.

The reason for repairs must be stated and those on account of damage, the alleged cause of which must be given, should be detailed separately from wear and tear repairs. State what action has been taken regarding items which are subjects of class. State also where appropriate, for the information of the Technical Records Dept., the material of the defective item and whether it is a forging, casting or welded fabrication. Any alterations in existing particulars in the Register Book should be reported above.



© 2021

Register  
Foundation