

26 FEB 1963

Ship's name

"LANTAO"

Port

H.Kg.

No.

17494

Last survey date 2.1.63.

GB Class is subject to

For conditions of class see previous endorsement.

ACTION is DEFERRED for Repairs.

S.R.L. Appendix (as before ~~XXXXXX~~)

Nature of present survey (afloat and in drydock)

Docking: Various damage repairs - part deferred.

Recommendation

SUBMITTED record of 'DS 1,63' be assigned subject to bottom shell plates B.2 & C.1 (p.s.f) being specially examined and dealt with as necessary next drydocking but without other condition.

DS 1,63 Subject Without.

S.R.L. APPENDIX NOTE (AMENDED).  
Indented shell plating (s.s.f)  
also shell plates C.3 & D.6 (p.s.f).



© 202

*R.S.P.*

15/2/63

C.S.S. Reports Dept.  
to note, see HW.  
Lloyd's Register  
Foundation