

Received from Chief Ship Surveyor.....15 MAY 1962

SHIP'S NAME "LANTAO" REPORT Bom. No. 15297

GB

Outstanding Conditions of Class: NONE.

S.R.L. Appendix. (As before ~~and xxxxxx~~)

Nature of Present Survey: (Afloat ~~and xxxxxx~~)

Deferred repairs on account of fire damage.

Recommendation:

SUBJECT to buckled centreline bulkhead
in No.2 hold (fire) being examined and
dealt with as necessary at the next
drydocking.

As Now. Subject

IN S.R.L. APPENDIX.
Indented shell plating (s.s.f).



Ships Register
Foundation