

COPY

Ship's name

"KOTEI MARU"

Port

(a) Phl.  
(b) N.Yk.

No.

11739  
61802

Last survey date

28.2.63.

GB Class is subject to

NONE.

S.R.L. Appendix (as before or none)

Nature of present survey (afloat and in drydock)

- (a) Examination afloat after grounding.
- (b) Damage (contact) involving shell plate H.15 (s.s) and shell plates in 2nd below sheerstrake in way of frs.165/167 (p.s).

Recommendation

NOTED.

SUBJECT to set in shell plate H.15 in way of No.2 hold (s.s.) and to shell plates in 2nd below sheerstrake in way of frs.165/167(p.s) being specially examined and dealt with as necessary next drydocking, ACTION is DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.

Drydocking (grounding).

IN S.R.L. APPENDIX.

Indents in shell plates in 'G' & 'H' strakes (p.s) in way of E.R.etc.

(Main structure partly of P.403 Steel)

End. S.1



© 2021

Lloyd's Register  
Foundation

8700-SITE20-11720