

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER

ALTERATIONS TO CONDITIONS OF ASSIGNMENT OF LOADLINES

Ship's Name KANCHADEYAOfficial No. -Port of Registry ColomboThis ship has been under survey at Lowestoft During Constructionon 22nd May 1959 and the following alterations to the conditions of assignment of loadlines have now been effected ~~found~~ ✓

Sidescuttles 8-8" diam non opening type side scuttles fitted in the engine room are fitted with portable steel deadlights fitted externally. ✓

Air Pipes 2-2" diam gooseneck type air pipes under bulwark rail 14 1/2 ft to store space, closed with wood plug attached by chain. ✓

G. Talbot.

Noted on Rpt. C. 11
H. J. 27.59

A copy of this Report has been placed on board.

