


COPY

LLOYD'S REGISTER OF SHIPPING

6739



Port.....*Yokohama*.....

Date.....*9th July, 1966*.....

This is to Certify *that I have*

surveyed the **S.S. "BOHNA", 6910** *gross tons of Panama*
on 5th July, 1966 and subsequently whilst afloat at Yokohama for General Examination for postponement of Special Survey (due 3.66) until vessel's arrival at Nagoya where now bound from Yokohama (in ballast)

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all repairs, recommended by me have been completed to my satisfaction, also that I am recommending that she be **continued as now classed without fresh record of Drydocking, subject to excessively corroded a) Wash bulkhead in No.3 deep tank b) No.2 deep tank (P & S) c) No.4 tween deck plating (P & S aft) d) lower end of shell frames in way of No.1 tween deck (P & S aft) e) Horizontal coaming bars of No.1 & 4 hatchways on upper deck f) No.4 hatchway coaming on upper deck(P) g) D.B. tank top in way of No.3 deep tank (P & S) (cement boxes previously fitted) h) No.1 hatchway coaming on upper deck (P)(now temporarily repaired) being dealt with at/by completion of next Special Survey at Nagoya and to all other outstanding conditions at present attached to the ship's class being dealt with as previously recommended.**

[Signature]
 Surveyor to Lloyd's Register of Shipping

V. WILKER

KEY TO ABBREVIATIONS

AS Annual Survey
 BIS Biennial Survey
 DS Docking Survey
 NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
 SS(Dr) Hull Special Survey (Drilling)
 SS(M) Hull Special Survey (Modified)
 CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"The Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, but it is to be understood that neither the Society nor any Member of any of its Committees nor any of its Officers, Servants or Surveyors is under any circumstances whatever to be held responsible or liable for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any act or omission, default or negligence of any of its Committees or any Member thereof, or of the Surveyors, or other Officers, Servants or Agents of the Society."

N. Cert. B 240m,9,65 (MADE AND PRINTED IN ENGLAND.)

012722-012727-0203