

COPY
LLOYD'S REGISTER OF SHIPPING



4157

UN RYONG
Port PUSAN
Date 7 March 1962
No. 4157
74-3-62
Accompanies
REPORT
Dated

This is to Certify that I have

Surveyed the m.v. " UN RYONG " 1049 tons gross of INCHON, on the
4 March 1962 and subsequently, whilst the ship lay afloat at PUSAN, for
examination of DAMAGE, stated incurred on the 4 February 1962 whilst the
ship lay alongside at the port of NAGOYA, Japan

and that I will transmit to the Committee of Lloyd's Register of
Shipping, London, a Report, stating that all repairs recommended by
me have been completed to my satisfaction, also that I will
Recommend that she be retained as Classed without fresh record of
Docking, subject to indented side shell plating (No.2 from forward in 1st
& 2nd below sheer, port side) being dealt with as necessary at completion
of SS (due 6/62).

J. Winn.
J. WINN

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
SS(P) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."