

COPY  
LLOYD'S REGISTER OF SHIPPING



4157

Port PUSAN

Date 7 March 1962

**This is to Certify that I have**

**Surveyed the** m.v. " UN RYONG " 1049 tons gross of INCHON, on the  
7th March 1962 and subsequently, whilst the ship lay afloat at PUSAN, for  
examination of DAMAGE, stated incurred on the 4 February 1962 whilst the  
ship lay alongside at the port of NAGOYA, Japan

**and that I will transmit to the Committee of Lloyd's Register of**  
**Shipping, London, a Report, stating that all repairs recommended by**  
**me have been completed to my satisfaction, also that I will**  
**Recommend that she be** retained as Classed without fresh record of  
docking, subject to indented side shell plating (No.2 from forward in 1st  
and 2nd below sheer, port side) being dealt with as necessary at completion  
of SS (due 6/62).

*J. Winn*  
J. WINN

Surveyor to Lloyd's Register.

KEY TO ABBREVIATIONS

AS Annual Survey  
BIS Biennial Survey  
DS Docking Survey  
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey  
SS(Dr) Hull Special Survey (Drilling)  
SS(M) Hull Special Survey (Modified)  
SS(F) Hull Special Survey (Progressive)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that :-  
"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly  
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances  
to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any  
entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its  
Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."