

"MARISIN M"

It is submitted the Naples Surveyors be informed in reply to their letter of 18th April that neither in the case of the "Marisin M" nor the "Conte Biancamano" will a BS record be assigned until the respective conditions of class have been dealt with.

It is the Committees normal practice to withhold a BS record when a short limit of six months or less is recommended and the defect is of a serious nature.

all

26.4.56.



© 2021

Lloyd's Register
Foundation

012744-012751-0213