

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

26th May, 1966.

C
DNS/CB

Dear Sirs,

Motor Vessel "SEVEN SEAS"

The Report of the survey carried out by the Colombo Surveyor on the 8th April, has now received the consideration of the Committee.

At that time the after starboard fresh water cooler was found to have 75 tubes plugged, and the water box and forward and after covers were found to be heavily corroded, and although considered efficient meantime it was recommended that this cooler should be examined and dealt with as found necessary by the end of July, 1966.

The Committee have continued the vessel's class subject, inter alia, to this matter receiving attention by that time.

Please inform the Owners accordingly.

The Donkey Boiler Survey became due at the end of March last, and I shall be glad to learn what arrangements the Owners propose to make to carry out this inspection.

Yours faithfully,

pro Classification Manager.

The Surveyors,
BREMEN.



© 2021

Lloyd's Register
Foundation

012796-012800-0023