

22 NOV 1962

Ship's name "PADEREWSKI" Port BDX No. 7089

Last survey date 19.10.62.

Class is subject to 15 fathoms of chain cable being supplied at the earliest opportunity and to permanent repairs to E.R. sea chest in No.6 D.B. tank (p.s) being permanently repaired next drydocking.

S.R.L. Appendix (as before ~~XXXXXX~~)

Nature of present survey (afloat and ~~in drydock~~)


Repairs to E.R. sea chest in No.6 D.B.tank.

Recommendation SUBJECT to 15 fathoms of chain cable being supplied at the earliest opportunity, without other conditions.

As Now Subject  
without.

IN S.R.L.APPENDIX  
(Main structure partly of P.5 Steel).

End. S.1



C.S.S. Records Dept.  
to note.

Lloyd's Register  
Foundation

012796-012800-0124