

COPY

LLOYD'S REGISTER OF SHIPPING



Port of Piraeus,

11th July, 1960.

This is to Certify that I have
 Surveyed the Machinery of the S.S. "MARCOS" 7033 tons gross of
 Piraeus whilst lying afloat & on the Govt. Floating Dock at Syra
 on the 24th May, 1960 & subsequently on account of Docking Survey
 & Part Engine Survey,

and that I will transmit to the Committee of Lloyd's Register of
 Shipping, London, a Report stating that all recommendations made by
 me in connection therewith have been carried out to my satisfaction; also
 that I will Recommend that in the case of this Vessel the following
 Survey Records be made in the Supplement to the Register Book
 S.S. 2,60 as previously recommended when the survey has been
 completed

and that her Machinery Classification Record be continued in the Book.
 without condition of class regarding the suction valve manifold
 of main engine after driven pump.

Parts now examined:

(C.S. Items only)
 Electrical Installation.
 Main Circulating Pump.
 Vaporator.

Complete Engine Survey.

vaporator to test hydraulically, & its safety valves to adjust
 under steam.

S. Blakemore
 Engineer Surveyor to Lloyd's Register

KEY TO ABBREVIATIONS

ABS Auxiliary Boiler Survey
 CS Continuous Survey of Engines
 DBS Donkey Boiler Survey
 ES Engine Special Survey
 MBS Main Boiler Survey
 MES Modified Survey of Oil Engines
 OF Fitted for oil fuel (date) FP above 150°F.

SGS Steam Generator Survey
 SPS Steampipe Survey
 TS Tailshaft Survey
 TS(CL) Tailshaft Survey—Continued
 TSN Tailshaft renewed
 TS(OG) Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly
 performed, neither the Society nor any Member of any of its Committees is under any circumstance whatever to be
 held responsible for any error in an entry or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other
 of the Society or its Surveyors, or in any judgment, default or negligence of any of its Committees or any Member thereof.

executed, it is to be
 responsible for any
 error of the Society
 or Officers or Agents