

Surveys must be reported in the terms of the Rules. The nature and extent of Examinations and Repairs (if any) must be stated in detail, the parts examined and their condition being clearly indicated. For Annual, Special or other Condition Surveys the Summary of

LMC
M
A
CL
a.

SEE ALSO ENDORSEMENT DATED 10.9.58.

19 JAN 1959

Received from Chief Ship Surveyor

NAME "BELLATRIX" REPORT Bmn. No. 4131.

standing Conditions of Class: Subject to side shell plates 2nd below sheer Nos. 5 & 7 etc. (s.s.f) being examined and dealt with as necessary and to shell, upper and bridge deck plating being permanently repaired by completion of the S.S.

ACTION IS DEFERRED FOR COMPLETION OF THE S.S.

sement of Class (B) (As before ~~XXXXXX~~)

ys due: SPECIAL SURVEY (O) due 2,58. Commenced Ham. 7,58. Postponement of completion of S.S. until 2,59 approved 2.10.58. G.E. completed Ham. 7,58.

e of Present Survey: ~~xxxxxx~~ and in dry dock)

Docking; examination of deferred items, as above.

al Features: -

terim Certificate in order (Yes ~~no~~ None)

~~Outstanding xxxxxxxx for xxxxxxxx~~

TO COMPLETE S.S.: See previous endorsement and list attached.

to be completed by: 2,59.

endation: SUBMITTED record of 'DS 12,58' be assigned SUBJECT as above, but FURTHER ACTION CONTINUE TO BE DEFERRED for completion of the S.S.

DS 12,58. SUBJECT.

S.S. PART HELD.

S.R.L. APPENDIX.

Indents in side shell plating (p & s). (Pitted bridge deck plating to be kept under observation).

8-1-59



© 2021

Lloyd's Register Foundation

012888-012897-0226

new)

Regis