

Received at

GREENOCK

Office

3<sup>RD</sup> OCTOBER 1933

(Report on Vessel No. *SS. "Arcagon"* Port *GREENOCK*)

Gen. List Entry Ref. No. 19448.

0. 456 SHIP ~~FORGINGS~~ OR CASTINGS.

I have to report that the undermentioned ~~Iron or Steel Forgings or~~  
Castings, manufactured by Stranmann Verksted  
of Stranmann for the Vessel No. 866, being built  
by Lillgreen & Co of Torshavn  
have been inspected by me as set forth below and found to be, so far as can  
be seen, sound and free from defects

~~Forgings or~~ Castings.


4.  
H. Lloyd's  
5.9.33.  
No. 8852  
P.B.R.

Dec 28/9.33.

Terzani River

	STERN FRAME.	RUDDER FRAME.	STEM.
* ... ..		Steel	
ade ... ..		cast	
aled ... ..		Yes	
ons ... ..		As per plan	
s on Inspection ...		Rough coated	
hen Inspected } CASTINGS. on Standard Test Pieces. <u>Test—</u> per square inch		23/8 x 25/9.33.	
asion per cent. ...		29.3	
<u>ending Test—</u> e before fracture		34.5	
<u>est—</u> ht from ground ...		180°	
<u>ering Test—</u> ade according to Rules d found satisfactory ...		8'	
		Yes	

SKETCHES OF FRAMES SHOWING POSITION AND DESCRIPTION OF WELDS OF FORGINGS.



fee (if any chargeable) Rs. 66.—

To be paid at Oro.

of Iron, state whether scrap or puddled Iron. If of Steel, state whether made on the Open Hearth process.

012888 - 012897 - 0233



Lloyd's Register  
Foundation