

COPY

DISCLOSED
SECTION
NO. 681

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
Overseas: Committee, London, E.C.3Telephone: ROYal 9166
Telex No.: 24305

16th March, 1962.

Dear Sirs,

Steamer "PRAMBANAN".


G.

AH/SM

I acknowledge receipt of your letter of the 14th February, the contents of which have been noted.

This case received the consideration of the Committee at their meeting today, and in view of the fact that the Owners have relinquished the Society's class without the wasted bottom and side plating, etc. being repaired, instructions were given for a notation to be recorded in the Register Book indicating that the class has been withdrawn on account of reported defects. Please inform the Owners accordingly.

Yours faithfully,

Deputy Clerk to the
Classification Committee.The Surveyors,
DJAKARTA.

© 2021

Lloyd's Register
Foundation

012966-012982-0112