

-3 JUN 1965

Ship's name "DJAJAPTRATAMA"

(a) ~~DJA~~ H.Kg. 19336
Port (b) Kob. No. 14327

Last survey date 3.5.65.

GB Class is subject to the rudder post and shell plate F.1 (p&s) in way of rudder post (E.W. and reinforced 5,64(being specially examined and dealt with as necessary next drydocking, to shell plate No.4 in 1st strake below poop sheer (s.s. from aft) being kept under observation (8,64) also to port lower anchor and 135 fms. of chain cable (p.s) (supplied Kob.12,64) being replaced by equipment of Rule weight and test at the earliest opportunity.

S.R.L. Appendix (as before ~~xxxxxxx~~)

Nature of present survey (afloat ~~xxxxxxxxxxxxxxxx~~)

- (a) Temporary repairs to bottom shell plating.
- (b) Examination afloat after grounding.

Recommendation

SUBJECT as above, and to the starboard side garboard strake bottom shell plating frs. 31/32 in way of No.4/5 D.B.cofferdam at fore end of E.R. being specially examined and dealt with as necessary next drydocking by 10,65, but ACTION be DEFERRED for examination in dry dock after grounding.

SUBJECT

INSERT IN S.R.L.

Drydocking(grounding).

IN S.R.L. APPENDIX.

Bottom shell 'B' strake (s.s.f) wavy.

Keel plate No.3 from aft waved.

© 2021
Lloyd's Register
Foundation
DJA 1/6/65