

COPY

# LLOYD'S REGISTER OF SHIPPING



Port SAINT JOHN, N. Z.

OCTOBER 16, 1962

**This is to Certify** *that I have surveyed part of the machinery of the* **M.V. "IRVINGDALE I"** **8454** *Gross tons, of Nassau for* **Continuous Survey of Machinery and Docking, while lying in drydock at Saint John on October 3, 1962 and subsequently,**

*and that all my recommendations have been carried out to my satisfaction. I am reporting accordingly and recommending to the Committee of Lloyd's Register of Shipping that the machinery classification should be retained and the following survey records assigned* **C.S. (with date) survey now having been completed, subject to ballast pump suction and delivery chest being renewed by April, 1963 (6 mos. limit).**

**Rarts now examined:—**

**MAIN ENGINE:**

No. 3 cylinder, liner, piston and piston rod.  
Top end bearing and pins with guide.  
No. 5 bottom end bearing and crankpin. Holding down bolts and chocks.

**AUXILIARIES:**

General Service pump (port side)  
Ballast pump (port side)  
Boiler F.O. transfer pump (stbd. side)  
Steam engine of steam hydraulic steering gear.  
Boiler F.O. service pumps (fwd. and aft stbd.)  
Port aft feed water pump.  
Auxiliary condenser.  
Fwd. and aft F.D. fans.  
Fuel Oil service heaters  
Fire extinguishing arrangements

**MAIN ENGINE DRIVER**

Lubricating Oil pump  
S.W. cooling pump

**DOCKING:**

All sea valves.

*A.K. McDougall*

**Surveyor to Lloyd's Register of Shipping**

**A.K. McDougall,**

**KEY TO ABBREVIATIONS**

ABS	Auxiliary Boiler Survey	MBS	Main Boiler Survey	TS	Tailshaft Survey
CSM	Continuous Survey of Machinery	OF	Fitted for oil fuel (date) FP above 150° F.	TS(CL)	Tailshaft Survey—Continuous Liner
DBS	Donkey Boiler Survey	SGS	Steam Generator Survey	TSN	Tailshaft renewed
ES	Engine Special Survey	SPS	Steampipe Survey	TS(OG)	Tailshaft Survey—Oil Gland

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."