

COPY

LLOYD'S REGISTER OF SHIPPING



Port ANTWERP.

Date 10th. November 1964.

This is to Certify that I have surveyed the ms. "ZAGORA". 1437 gross tons of Casablanca whilst lying afloat in this port between the dates 8th. and 10th. November for damage, temporary repairs, and examination and part completion of Casablanca recommendation for Condition of class,

and that I am transmitting to the Committee of Lloyd's Register of Shipping, London, a report, stating that all temporary & permanent repairs recommended by me have been completed to my satisfaction, also that I am recommending that she be continued as now classed without fresh record, subject to "the soft nose stem plates (indented) and the following "set in" or indented shell plates, 1st. & 2nd. from forward in the 1st. strake below shelter deck sheer (s), the 1st. (p&s) and 4th. from forward and the 5th. from aft (p) in the 2nd. below shelter deck sheer, and the 1st. from forward (p&s) in the 3rd. and 4th. below shelter deck sheer, all to be further examined and dealt with as considered necessary at the next drydocking (about 1 month limit), and without condition regarding renewal of air pipe gauzes, and repairs to shell plate P5 (p) and internals (3 months limit) but subject to any other conditions which may at present be attached to the ship's class being dealt with as previously recommended."

J. BOYLAN.

Surveyor to Lloyd's Register of Shipping

KEY TO ABBREVIATIONS

AS Annual Survey
BiS Biennial Survey
DS Docking Survey
NS Cargo Battens not fitted (No Sparring)

SS Hull Special Survey
SS(Dr) Hull Special Survey (Drilling)
SS(M) Hull Special Survey (Modified)
CSH Hull Special Survey (Continuous)

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."