

30.11.64.

XXXXXXXXXX

FALMOUTH

PORT JACKSON.

9827

Subject to rudder lower pintle and gudgeon being specially examined
**NDD

See No 227.

See No 14.

NIL

5

D.B.S. Due 11.64 To complete, safety valves of the upper boiler
to adjust under steam.

CFF
6.11
C.S.M. Cond(M).



© 2021

Lloyd's Register
Foundation

013961-013971-0032