

Lloyd's Register of Shipping.

FOUNDED 1760.


RE-CONSTITUTED 1834.

Certificate of Class

Steel Screw Motorship "Batavier"
 Official Number *5* Port of Registry *Groningen*
 Owners *J. Muthert*
 Builders, and where and when Built *Gebr. Niestern & Co, Delfzijl, June 1941*

REGISTERED PARTICULARS.

| | |
|---------------------------|--------------------------------|
| Length <i>183.0</i> feet | Tonnage, Gross <i>394.96</i> |
| Breadth <i>28.06</i> feet | Ditto under Deck <i>239.11</i> |
| Depth <i>6.53</i> feet | Ditto Net <i>147.58</i> |

This is to Certify that this Vessel has been built under the Special Survey of the Surveyors to this Society, and was reported to be, on the *1st August 1947* in a good and efficient state, and fit to carry dry and perishable Cargoes, and has been **CLASSED** and entered in the **REGISTER BOOK** of this Society, with the Character  *100A1 Specially Surveyed Groningen 8.47* with freeboard subject to Periodical Surveys as required by the Rules.

THE FREEBOARDS FROM THE DECK LINE ARE AS FOLLOWS:—

| | |
|--|---|
| Tropical <i>5 cms.</i> feet <i>inches</i> (T). | Winter North Atlantic <i>15 cms.</i> feet <i>inches</i> (WNA). |
| Summer <i>5 cms.</i> feet <i>inches</i> (S). | Allowance for fresh water for all freeboards <i>6 cms.</i> inches |
| Winter <i>10 cms.</i> feet <i>inches</i> (W). | |

Witness my hand,

P. Clement

Secretary.


R. A. A. A.
Chairman.

71, Fenchurch Street, LONDON. *19th September 1947*

N.B.— If the vessel herein named proceed to sea with a less freeboard than that assigned, or if the freeboard marks be obliterated or placed higher than the correct position, the class will be liable to be forfeited.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, to which Owners are referred, and which provide that:—

"While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."



© 2021

Register
Foundation



© 2021

Lloyd's Register
Foundation

014004-014014-0029