



# Lloyd's Register of Shipping,

18, Burlington Road,

Ipswich, 15<sup>th</sup> February 1928

LLOYD'S REGISTER  
RECEIVED  
16 FEB 1928  
LONDON

Dear Sir.

In reply to your letter of the 14<sup>th</sup> instant  
respecting the First Entry report No. 92280 on the machinery  
of the S.S. "Robin," I have to state that the thrust shaft diameter  
under the collar is 6 inches, not 5.75 inches as entered on my report.

I am, Dear Sir

Yours faithfully,  
A. E. Farminer.

The Secretary  
London.



© 2021

Lloyd's Register  
Foundation

014753-011262-0283



Referred to the Chief Engineer Surveyors

RAM,

16 FEB 1928

Also for Mr. S. A. Hill to note.

Noted as above  
10/2/28



© 2021

Lloyd's Register  
Foundation