

DISCLOSED
SECTION
No.

DISCLOSED
SECTION

(Received at London Office)

hon No. 126177 A.

REPORT OF SURVEY FOR REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of...

No. in Reg. Book Survey held at Date, First Survey Last Survey 19...

17059 91627 on the Wood Iron or Steel MV "LANTYAN" Thorne, Doncaster

TONNAGE 313 Built at By whom R. Dunston Ltd. When 1943 MONTH 8

GROSS 219 Owners Lowey Harbour Commissioners Owners' Address

UNDER DK 143 Managers Port belonging to Plymouth

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

Cell D Bor D Ba feet: uE&B feet: f feet

total capacity tons. FPT tons: APT tons: MT feet tons.

Only alterations in the existing records of tanks should be inserted.

N.B.—All alterations in the existing records should be underlined.

Last Report, No. 124306. Port Lon.

Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and in detail the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

In damage cases where the Surveyor has not made a special damage report, he is required to state whether he offered his services for this purpose and to whom and why they were declined.

Was a damage report made by anyone else? if so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE FOR

OIL ENGINES
CONTINUOUS SURVEY

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors.	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed, ...								
Removed and Fair'd or Repaired								
Fair'd or Repaired in place								

PRESENT CONDITION OF THE	Bulkheads	Engine Room Skylights	Copper, or Y.M.
Plating of Decks	Ceiling	Coal Bunkers, Openings, Covers, &c.	(State if on Felt.)
Stowings	Cement or Asphalt	Oil Bunkers	When fitted, Month Year
Stowings & Fastenings	Rudder	Scuppers	Boats
Side Plating	Steering gear and its connections	Cargo Hatchways	Masts, Yards, &c.
" " in way of sidelights	Windlass	Hatches	Condition, how ascertained
Stowings	Have pumps been examined and found efficient?	Planking	(State if wedges removed.)
Stowings	Have Sluice Valves been examined and found efficient?	Caulking	Equipment letter
Stowings	Have Watertight Doors been examined and found efficient?	Treenails	Anchors, No. of
Stowings	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson	Cables (State if now ranged)
Stowings	Air and Sounding Pipes	Transoms, Pointers & Crutches	" length mean diam.
Stowings	Doubling Plates under Sounding Pipes	Timbers of Frame at openings	(on board.)
Stowings		" " at other places	" Rule length size
Stowings		Stringers, Clamps & Shelves	Chain Locker
Stowings		Saltine	Hawser & Warps
Stowings		(State if examined)	Standing and Running Rigging
Stowings			Sails

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:— "to remain as classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,38," or "to remain as classed and to have record of survey, 1,38, and the notations of ss No. 1-38."

Survey Fee (per Section 23)	£	:	:	Fees applied for,
Special Damage or Repair Fee (if any) (per Sec. 25)	£	:	:	19...
Travelling Expenses (if chargeable)	£	:	:	Received by me,
Second Surveyor's Fee (if any)	£	:	:	19...

Committee's Minute

Character Assigned

FRI. 1 MAY 1953

GENERAL COMMITTEE

Thursday 24 September 1953
Classing Committee's decision confirmed.

Surveyor to Lloyd's Register of Shipping

FRIDAY 14 AUG 1953

Lloyd's Register Foundation

014513-014530-0297

Deferred
for this year

When Anchors or Cables are supplied, the particulars are to be reported in the following form:—

Number of Certificate.	Anchor. ^a	WEIGHT EX. STOCK.		WEIGHT OF STOCK.		TEST PER CERTIFICATE.			WEIGHT REQUIRED BY RULE.		Description of Anchor.	Makers.	Where and when tested and Superintendent.
		Cwts.	qrs. lbs.	Cwts.	qrs. lbs.	Tons	Cwts.	qrs. lbs.	Cwts.	qrs. lbs.			
	1st Bower												
	2nd "												
	3rd "												
	Collector's Weight												
	Stream												
	Kedge												

If Patent, state name of Patentee.

If Stockless, state Mechanical Test.

• When a bower anchor is supplied it must be clearly stated whether it is a 1st, 2nd, or 3rd bower.

[illegible]

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN