



# Lloyd's Register of Shipping,

810 Merchants National Bank Bldg.,

Mobile 11, Ala.

June 4th 1953

AIRMAIL

RECEIVED

E 8 JUN 1953

Classn (S)

The Secretary  
Lloyd's Register of Shipping  
71, Fenchurch Street  
London, E.C.3, England

Dear Sir:

"RAPHAEL SEMMES"


I am in receipt of your letter of the 28th May 1953 suggesting that documentary evidence of the adjustment of the port boiler safety valves on the above named vessel be submitted to the Committee with a view to being accepted as completion of the Boiler Survey.

The Owners have supplied a photostatic copy of the American Bureau of Shipping Philadelphia Report of the 3rd October 1952, wherein it is stated the port boiler was examined and the safety valves adjusted.

A photostatic copy of the U.S. Coast Guard Certificate of Inspection dated 7th October 1952, at Baltimore, was also supplied. This certificate is only issued when the complete boiler survey including adjustment of safety valves has been completed.

The two documents referred to are enclosed for submitting to the Committee.

Yours faithfully,

  
Surveyor

WFC/nv

Encls. 2

cc N.Y.

cc Philadelphia



© 2021

Lloyd's Register  
Foundation

014631-014641-0276

014631-014641-0277



ER

CLASSIFICATION

H

2017

A handwritten signature in dark ink, appearing to be 'R. S. D.' with a large, stylized flourish at the end. The signature is written on a light-colored, textured paper.

THE END OF THE WORLD

DEPT. OF AGRICULTURE

11200000 10000000

Толсон, Р. С. Э., 1957 г. 100

1. The first part of the text discusses the importance of maintaining accurate records of all transactions, including sales, purchases, and expenses. It emphasizes that proper record-keeping is essential for determining the correct amount of tax liability.

Sept 1896

© 2021

Lloyd's Register  
Foundation

Wopie, SIA