

s.s. "AUDAX"

The class of this ship was expunged with a black line on the 8th ultimo because the Owners failed in their promise to present the boilers for re-examination before the expiry of a limit, and because the Owners wished the Society's classification to be terminated.

In view of the Owners' protest at the above decision, the case was again considered and the Committee decided that the class should be expunged with a red line.

The Owners now submit that the Society's Surveyors may be permitted to carry out the re-examination of the boilers, and on receipt of a satisfactory report, the Committee might consider that the class be withdrawn at the Owners' request and (...) substituted for the red line.

The matter is submitted for the consideration of the Committee.

17th January, 1951.



© 2021

Lloyd's Register  
Foundation

014675-014685-0015