

1 E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

SHIP NAME "MOONLIGHT" REPORT Liv. No. 135496 Gls. 78362

Remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

(The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement.—Extract from Sub-Committee's Report, 24/5/92.)

Type of Engine Compound 11 1/2" x 24" - 18" H.S. 630 sq.ft. NEW MN 40

If-Boilers-fitted-with-forced-draught

Tail Shaft. If fitted with a continuous liner Yes If fitted with an outside gland of approved type No

This vessel's machinery appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed * IMC 4.52, 1 SB 140 lb.

End

14. 7. 52.



© 2021 Lloyd's Register Foundation

0148 27-014834-0136