

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

C
MWK/GDF

15th June, 1965

Dear Sir,

CLASSING LETTER

4276 "LUCIANO CASTRO." The contents of your Report have been noted and reinstatement of class has been deferred pending the renewal of 165 fathoms of worn chain cable and the supply of 30 fathoms of chain cable. It is noted from your Report that the Owners have ordered this cable and that delivery may take 6/9 months, and I shall be glad if you will keep me advised of the position regarding this matter.

Please confirm that the Main Engine crankpins and bearings were examined in view of the fact that these have been omitted from the Report, but included on the Interim Certificate.

4307 "PRESIDENTE DUTRA". As recommended except that class has been continued subject to the laminated deck plates in way of No. 9 cargo tank (port side) midway between Nos. 8 and 9 tank cargo hatchways being specially examined and dealt with as necessary by November 1965.

Yours faithfully,

pro Clerk to the
Classification Committee.

C.A. Davies, Esq.,
SANTOS



© 2021

Lloyd's Register
Foundation

014835-014842-0211