

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

13th October, 1965

C
MWK/GDF

Dear Sirs,

CLASSING LETTER

909,16 "KAREEM" As recommended. I would refer you to the entry in the S.R.L. Appendix regarding indented shell plates, and it is concluded that these were examined and found efficient, but your confirmation is desired.


I shall be glad if you will ascertain from the Owners what early arrangements they propose to make to supply the necessary chain cable.

It would appear from our records that the starboard 120 K.W. auxiliary engine and the diesel oil fuel transfer pump have not been seen for four years, and the Owners should be requested to make arrangements for these items to be examined at an early date.

Yours faithfully,

The Surveyors,
KARACHI

pro Clerk to the
Classification Committee.

 Lloyd's Register
Foundation

014873-014886-0307