

COPY.

Lloyd's Register of Shipping.



Port of BREMEN.

Augsburg, 22nd January, 1930.

08177X
20082
28
101080/90
04Vu33
Lloyds 860.

This is to Certify that

Victor Sdrowok

the undersigned Surveyor to this Society did at the request of Messrs. Maschinenfabrik Augsburg-Nürnberg A.G. attend their works on various dates for the purpose of testing and inspecting two seamless Siemens-Martin steel air receivers, ordered by Messrs. Compania Arrendataria del Petroleos of Madrid and destined for their M.V.506.

SPECIFICATION.

No. of rec.	outs. diam.	Thickness of shell	Length of rec.
2	440 mm.	17.5 mm.	1300 mm.

For results of tests see Certificate P.9289, sample No. 17/18 P.K.

Hydraulic tests:- 60 kg cm².

Working pressure not to exceed 30 kg cm².


For identification the receiver has been stamped:-

No.860.
Lloyds test
60 atm.
W.P. 30 atm.
V.S.22.1.30.

sgd. V.Sdrowok
Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:-
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, or other Officers or Agents of the Society."



101080/90
04Vu33
Lloyds 860.

015276 015033-4158