

TELEPHONE: SUNDERLAND 4093 (2 LINES).

All communications to be addressed to
THE SURVEYORS.

Reference

"S"

Lloyd's Register of Shipping.

RECEIVED

9 JUN 1948

ANZ

55, Fawcett Street,

Sunderland, 7th June, 1948.

Dear Sir,

In reply to your classing letter of the 4th June respecting the motor vessel "INTERPRETER", we beg to state the 1" & 7/8" diameter rivets in the seams of the shell plating are in accordance with Table 40 of the Rules for 29" frame spacing, the spacing being 4.1/7" & 3.5/8" respectively.

In way of the bridge and clear of the breaks 7/8" dia. rivets with Rule spacing have been used in the seams and end laps of the sheerstrake and strake below; the butts are treble riveted.

It is regretted this was not made clear in the report.

Yours faithfully,
THE SURVEYORS,
PER:

Nail F. H. Duncan

The Secretary,
LONDON.



Lloyd's Register
Foundation

015183-015182-0152

Referred to the D.O

28

For Slip Surveyors (F.E. Rpts.) to note.

J.C.D.



© 2021

Lloyd's Register
Foundation

5" 1/2
1/2

