

No. 11.49.

4 E

Received by Chief Engineer Surveyor

Received from Chief Engineer Surveyor 3 - JUN 1950

VESSELS NAME

"L.C.9"

REPORT

Fly.

No. 8016

The remarks of the Chief Engineer Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/52.)

Nature of Survey


~~REPAIRS TO ENGINES AND BOILERS DUE TO DAMAGE THROUGH~~

This case is stated in an endorsement dated 24. 10. 49.

A Special Survey for reclassification has now been held.

The machinery, boilers and electrical installations examined. All plain tubes in both donkey boilers renewed and electric wiring renewed in part. The safety valves of the donkey boilers have been adjusted by H.M. Dockyard officials in the presence of an Engineer officer and IT IS SUBMITTED this be accepted by the Committee.

IT IS SUBMITTED that this vessel is eligible for the record BS 4.50.



© 2021

Lloyd's Register  
Foundation

2. 6. 50.

015224-015232-0311