

COPY

# LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex  
Overseas: Committee, London, E.C.3

Telephone: ROYal 9166  
Telex No.: 24305

24th April, 1967.

Dear Sirs,

C.  
CGB/DIST

## CLASSING LETTER

27856 "CRAFTSMAN". As recommended except that a record of ES 2.67 has been assigned.

27837 "VITTANGI". As recommended except that it is considered that the main engine No.7 cylinder in way of the scavenge belt and parts should be examined again before the end of February 1968 and the machinery class has been continued subject, inter alia, to this matter receiving attention by that time.


The class has also been continued subject to the evaporator not being used until surveyed.

With reference to Instructions to Surveyors, Part 3a, 1963, Amendment No.13, Paragraph 4, I shall be glad if, in this and future similar cases, you will state if these arrangements are in accordance with the appropriate section of the Rules.

It is concluded that the wear and tear repairs regarding the pittings in the bottom shell plates refer to the plates reported pitted on your Rpt.8 (DR).

27834 "PRINS DER NEDERLANDEN". As recommended except that a record of ES 2.67 has been assigned.

With reference to the Section of the Instructions to Surveyors quoted in the case of the "VITTANGI", I shall be glad to learn whether



015264-015272-0138 1/2

these arrangements are in accordance with the appropriate section of the Rules.

27900 "OOSTKERK". As recommended, except that a record of ABS 7.66 has been assigned.

Yours faithfully,

pro Classification Manager

The Surveyors,  
AMSTERDAM.



© 2021

Lloyd's Register  
Foundation

0138 2/2