




EXTRACT FROM CLASSING LETTER SENT TO SOUTHAMPTON  
DATED 8.2.57.

23899 and 23975 "CAPETOWN CASTLE" - As recommended, except that notations of SS(P) 17,55 and +LMC(CS) 11,55 have been assigned.

I think it well to point out that the holding down bolts and chocks of both engines, the starboard main engine aft scavenge blower, No.10 crankpin and the evaporator have not been surveyed for more than four years. The Owners should be informed accordingly and arrangements made for these parts to be inspected at an early date. Please let me know the Owners' proposals in this respect. I acknowledge receipt of your letter of the 17th January, with its enclosure, the contents of which have been noted.

23908,09,82 - As recommended.



© 2021

Lloyd's Register  
Foundation

015348-015354-0010