

GB

Outstanding Conditions of Class:

Subject to defective shell rivets in

OF SHIPPING

LLOYD'S REGISTER OF SHIPPING

4, Canute Road, Southampton

Telephone: Southampton 203537

Telegrams: Register

RECEIVED

17th January, 1957.

The Secretary,
London.

21 JAN 1957

Rec'd.

82

Dear Sir,

M.V. "CAPETOWN CASTLE".

The above vessel has been under survey at
this Port, see Report No. 23975.

It is regretted that the Ship side discharge
valves were omitted from the Certificate issued at that
time.

An amended copy of the Certificate is
enclosed herewith and we regret that this error has
occurred.

Yours faithfully,

K. Lygga

pro The Surveyors.

© 2021

Lloyd's Register
Foundation

500 3/1/12
Enclosure.

015348-015354-0011

Without.

EMBODIMENT OF CLASS (B)

