

COMMITTEE LDN
OSEAGRAM 06 LN

MTX18 TQSA857 KC 19 AI 50
KARACHI CITY 54/53, 13 1015 VIA IMP

LT
COMMITTEE LONDONEC3

REURCAB FATEHABAD ELEVENTH INSTANT
STOP BEING GUIDED BY YOUR LETTER 14TH SEPTEMBER
PLATES AT PRESENT SUBJECT OF CLASS EXAMAINED AND SUBMIT FURTHER
EXTENSION UNTIL APRIL REASONABLE STOP REFERENCE NEW
RANGING DAMAGE PORTSIDE ADDED YOUR INFORMATION STOP
PLEASE CABLE IF NOT AGREEABLE AS TEMPORARY REPAIRS
RANGING DAMAGE DUE COMMENCE STOP LLOYDREG

COL 14TH
SENT 0032/14TH MM

OSEAGRAM 06 LN
COMMITTEE LDN

CABLE IN

14 DEC 1967

CHG 7.11

RECEIVED
1967



© 2021

Lloyd's Register
Foundation

015483-015495-0167

Reports

SP/ER

AD
Submitted the Karachi Surveyors
be advised, provided they are satisfied
with the condition of ship after ~~pass~~
temporary repairs to varying damage the
purposement of SS until 4.68 should be recommended.
14-12-67.



© 2021

Lloyd's Register
Foundation