

by Chief Ship Surveyor 6/7/05

Received from Chief Ship Surveyor \_\_\_\_\_

EL'S NAME Sta Br. "Dalrymple" Rpt. By No. 7628

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinet summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement." - Extract from Sub-Committee's Report, 24/5/92.)

DAMAGE.

of Survey \_\_\_\_\_

Damage through stress of weather

now repaired as follows:-

	Plates	Frames	R. Frames	Floors	Beams	Str. Plates	Dk. Plates
Renewed .....							
Removed and faired or repaired.....							
Faired or repaired in place.....							

Other items:- Decks unworked, fore main rigging  
upper, stripped & recovered & rigging partly unworked,  
several spars unworked & minor repairs.

It is submitted the vessel is worthy to remain as classed with  
record of Survey 6.05 as recommended.

100 A 1  
6.05 By



2021  
6/7/05  
Lloyd's Register  
Foundation