

COPY.

Lloyd's Register of British & Foreign Shipping,

71, Fenchurch Street, E.C.

31st January, 1913.

Gentlemen,

With reference to the case of the steamer "CORNWALL"
S. I have to acquaint you that Representatives of the intending purchaser called at this Office this morning and stated that in removing a stud bolt from the sole piece of the stern frame a cavity was discovered which could not be seen at the previous examination.

In the circumstances it was thought desirable that Mr. Hand should make a further examination of the sole piece in way of the stud hole with a view to his reporting the result of his examination to the Committee as early as possible.


I therefore telegraphed to you as follows which I now confirm:-

"CORNWALL it is stated that in removing stud bolt from sole piece of stern frame a cavity was discovered not previously visible request Hand will make further examination of sole piece earliest possible before steel shoe fitted and report result".

I am, Gentlemen,
Your obedient servant,

The Surveyors,
CARDIFF.

Assistant to the Secretary



© 2021

Lloyd's Register
Foundation