

Received by Chief Ship Surveyor 27/7/03

Received from Chief Ship Surveyor _____

VESSEL'S NAME SS Captain Mc. Clure Report Dub No. 2192

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey Condition

This vessel has been examined in dry dock, the bottom cleaned and coated, and the following repairs done due to wear and tear;— the face angles on web frames strengthened, and minor repairs. The main hatchway has been altered to the Surveyor's satisfaction.

It is submitted the vessel is worthy to remain as classed with record of survey, as recommended.

100A-1
7-03 Dub

© 2019
Lloyd's Register
Foundation
DUB98-0142

this survey, thus, for example:—".....to remain as now classed in the Register book without fresh record of survey, to remain as classed survey, 1,98," or "to remain as classed and to have record of survey, 1,98, and the notations of ss No. 1-98 and ptND98, &c.."