

# Report of Survey for Repairs, &c., of Engines & Boilers.

No. 4014

(Received at London Office,

MONDAY 29 JUNE 1885,

No. in  
Reg. Book.

Survey held at

Glasgow

Date, first Survey

June 13<sup>th</sup>

Last Survey

June 15<sup>th</sup>

1885

862 on the Machinery of the

S.S. "Clan Stuart"

(Number of Visits

4

Year Month

Tonnage, Gross 2094

Built at

Dumbarton

When built

1879

Ditto, Net 1355

Owners

Cayzer Irvine & Co

Port belonging to

Glasgow

Diameter of Cylinder 36" & 46"

Engines made by

David Rowan

When made

1879

Length of Stroke

42"

Boilers made by

"

"

When made

1879

Pressure of Steam

80 lbs

If Surveyed Afloat or in Dry Dock

(State name of Dock.)

J. W. Henderson

Dry Dock

Classed

100 A1

Registered Horse Power 210

1.85

Last Survey No.

Port

L.M.C. 1.85

## Particulars of Repairs and Examination

(State clearly the cause of Repairs if any, and, in detail, the nature and extent of Examinations and subsequent Repairs. Repairs on account of Damage should be separated from Repairs due to other causes. State also the dates and initials of any letters respecting this case.)

Propeller, Boss, and one blade renewed also other two of the blades repaired by casting pieces on the points. Propeller Shaft drawn and examined.

On account of Damage caused by the vessel grounding and propeller striking some hard substance when entering Lyle Bay Harbour in March last

## General Observations, Opinion, and Recommendation :—

(State clearly what alteration, if any, is suggested to be made in the existing notification of the vessel's machinery in the Register Book, consequent upon this survey.)

The above repairs have been satisfactory Completed, and I am of opinion the vessel is eligible to remain as Classed

Fee or Registration Fee (per Sec. 27) £ : : :  
Survey Fee (per Section 28) £ : : :  
Additional Damage Fee (per Section 28) £ 2 : 2 :  
Certificate (if required) £ : : :  
Travelling Expenses (if chargeable) £ : : :  
received by me 25/6/1885

Committee's Minute

TUESDAY 30 JUNE 1885

Assigned

James Morrison  
Engineer Surveyor to Lloyd's Register of British and Foreign Shipping.

Clyde District

Lloyd's Register  
Foundation

GLS150-0382



7014. gls.

It is submitted that this vessel  
is eligible to remain as classed

D.A.  
29/6/85.