

New Springs fitted to Donkey Boiler
Safety Valve.

134578

N.B.—If this Report is copied by Copying Press, especial care must be taken that the copying paper is not so much damped as to spread the ink, or cause it to show through to the other side.

Two of the rods renewed & new
Liner fitted to A. P. Cylinder

It is submitted that
this vessel is eligible for
THE RESCUE. D. S. 10,944 to
have her name expunged
from the Register
for D. B. Crown May

J. P. P. P.
9295

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THIS MARGIN.



© 2019 Lloyd's Register Foundation