

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 18. When handed in at Local Office 18. Port of Glasgow
No. in Reg. Book 172 Survey held at Glasgow Date, First Survey 13th August Last Survey 14th August 1895
on the Wood, Iron or Steel Steamer "Pegu" (No. of Visits 2) Master Taylor

TONNAGE: - Built at Dumbarton By whom W. Penny & Sons When 1889 4
GROSS 3661 Owners British Assurance S. S. Co. (Lim) Port belonging to Glasgow
UNDER DE. 3317 Owners' Address
NET 2391 (if not already recorded in Appendix to Register Book.)
Surveyed Afloat or in Dry Dock? Dry Dock Name of Dock Headrowside Destined Voyage Rangoon
WB=Ceild B&D Ba tons; uE&B 235 tons; f tons; }
FPT tons; APT tons; MT tons. }
N.B.—All alterations in the existing records should be underlined.

If the vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.
Last Survey, No. 8 Port Rangoon
Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).
CHARACTER: * for Special Survey Date of last Survey and of Periodical Surveys. Machinery and Boiler Surveys (including date of N.B., if any).
100A.1 1.95 2.94
S.S. No. 121.93 B.S. 5.95
Society's Freeboard (if assigned) as painted on Ship and now verified ft. ins.

REPAIRS, OR EXAMINATION AS PER RULE, FOR Docking

This vessel has been placed in dry dock the bottom, cleaned, examined and recoated, rudder pintles bushed and lower pintle renewed, a large number of bolts at bilge cleaned out and refilled with cement stopping, a few rivets at stern frame renewed.

The laminated plate on port side forward mentioned in the and Secretary's letter of 23 July 1895 Rangoon Report No. 81 has now had the laminated portion cut out, a flush piece fitted in way of same and a doubling plate fitted on the inside the full breadth of plate and extending from frame to frame.

SUMMARY OF DAMAGE REPAIRS:—	Plates.	Frames.	R. Frames.	Floors.	Beams.	Other Items:—
Renewed ...						
Faired or Repaired ...						
PRESENT CONDITION OF THE	Timber of Frame at the openings ... <i>good</i>	Rudder ... <i>good</i>	Hatches ... <i>good</i>	Decks ... <i>good</i>	Ditto ditto at other places ...	Boats ...
Waterways ...	Keelsons ...	Windlass & Capstan ...	Masts, Yards, &c. ...	Coamings ...	Clamps, Shells & Stringers ...	Condition, how ascertained ...
Up'r Dk. Beams & Fastenings ...	Clamps, Shells & Stringers ...	Pumps ...	(State if wedges removed ...)	Low'r Dk. Beams & Fastenings ...	Stairways ...	Sails ...
Plating ...	Cement ...	Sluice Valves ...	(State if examined.)	Planking ...	Ceiling ...	Equipment letter ...
Tonnage or Rivets ...	Tanks ...	Watertight Doors ...	(State if new tested.)	Breasthooks & Stemson ...	Caulking of Bot'm, D'k, & Wat'rw'ys ...	Anchors, No. of ...
Transoms, Pointers, & Crutches ...	Copper ...	Db'ng. Plates under Sounding Pipes ...	(State if on Felt.)	Transoms, Pointers, & Crutches ...	When put on ...	Cables (State if now ranged) ...
		Engine Room Skylights ...	Year ...			" length ... size ...
		Coal Bunker, Open'gs, Lids, &c. ...				" Rule length ... size ...
		Scuppers ...				Hawsers & Warps ...
		Cargo & Main H'tch'w'ys ...				Standing & Running Rigging ...

General Observations, Opinion as to Class, Recommendation, &c.:—
State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 9,91," or "to remain as classed and to have record of survey, 9,91, and the notations of ss No. 1-91 and pND91, &c."
This vessel is in our opinion eligible to remain as classed and have record of survey 8.95

Office Fee (if chargeable) per Scale II, Sec. 27	Fees applied for,
Survey Fee (per Section 29)	18
Special Damage or Repair Fee (if any) (per Sec. 28.)	
Travelling Expenses (if chargeable)	18
Second Surveyor's Fee (if any)	

Received by me, *J. H. H. H.*
Surveyor to Lloyd's Register of British & Foreign Shipping.

Committee's Minute TUES. 20 AUG 1895
Character assigned 100A.1

