

Sent to Chief Surveyor 30. 4. 94.

Received from Chief Surveyor

VESSEL'S NAME *Irish S.S. "Crown of Arragon"* Report *Glo.* No. *12899*

The remarks of the Chief Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey

*Damage*

Damage by stress of weather: vessel examined in dry dock: 2 bulb beams fitted in way of mainmast and mainmast step fitted to same: tunnel repaired and other minor deck damage made good: 2 bower anchors of sufficient weight and properly tested supplied to complete the equipment and one repaired <sup>length</sup> ~~top~~ of cable re-tested.

It is submitted the vessel appears worthy to remain classed 100A1 with record of survey 4, 94 as recommended.

100 A1  
4. 94.



*G.B.*  
© 2021 *W.Ly*  
30. 4. 94.

Lloyd's Register  
Foundation