

Reference

E.

Lloyds Register of British
and Foreign Shipping.

Glasgow

19th May 1894

LLOYDS' REGISTER
LONDON.

RECEIVED 21 MAY 94

ANSR

Enc
Enc

Sir,

I beg to acknowledge
your letter of yesterday's date regarding
recommendations made in Glasgow
Report No. 12954 on the machinery
of the S.S. "Holme Wood" and in
reply I beg to state that the
Engineer of the Steamer informed
me that the vessel had just come
off the Slip at Barrow and that
the machinery was examined
by the Society's Surveyors at that
place, under those circumstances
I made the recommendation of
H.M.E. 5.94 knowing that the
Committee could verify the above
Statement from the Report of
the Barrow Surveyors. With regard

to seeing the engines working, I did not consider this necessary as everything appeared in good order. - The boiler, which was made in 1891, has been lying under cover at Messrs Hutson & Sons works since that time, was again examined before being put on board and was as good as the day it was tested. The plan of the boiler is herewith enclosed. - Trusting the above explanations will be considered satisfactory.

Yours Sir
Your obedient Servant
John Sanderson

The Secretary
Lloyd's Register
London



© 2021

Lloyd's Register
Foundation

0041^{2/2}

Referred to the Chief Engineer Surveyor.

afw

21/5/94



© 2021

Lloyd's Register
Foundation