

Average space...

Angle Irons on ditto, No. 2  
Tie Plates, outside Hatchways ...  
pairs

*Off.*

**FREEBOARD MARKED ON SHIP.**

FREEBOARD of the Tally of Earn  
Freeboard assigned 5-8 in Salt Water.  
Ditto 5-3 in Fresh Water.  
Ditto 6-2 in Winter, in Atlantic.  
Moulded depth for record 26-1

Per Freeboard Report NO

30<sup>th</sup> June 1884  
Fee Nil paid.

*J.H.C.*



© 2019

Lloyd's Register  
Foundation

GRK303-0017

The **REVERSED ANGLE IRONS** ON BUTTS AND KEELSONS.  
**KEELSONS.** Are the various lengths of Plates and Angle Irons properly connected? Yes And butts properly shifted?